

Subject: Re: Additional materials
Date: Friday, January 2, 2004 8:17 AM
From: BSmith@maximcrane.com
To: Susan Podziba <susan@podziba.com>

Docket S030
Ex. 43-8

14XX Signal Person Qualifications

(e) Qualification Requirements. Each signal person must:

- (1) Know and understand the Standard Method (see Appendices __, __, and __) for the type of signals used.
- (2) *Be competent in the application of the Standard Method for the type of signals used, in light of the equipment and conditions at the site.*
- (3) Know and understand crane dynamics in swinging and stopping loads
- (4) Know and understand boom deflection when hoisting loads

Bill Smith
Corporate Safety/ Labor Relations Manager
Maxim Crane Works
508-C DiGiulian Blvd.
Glen Burnie, MD 21061
410-582-9106 Baltimore
410-371-6308 Cell